

Vedr.:  Stokkeholder Rep kit	PUP nr.:	23-004
	Udarbejdet af:	LPA
	Dato:	15-11-2023
	Intern <input checked="" type="checkbox"/>	Ekstern <input type="checkbox"/>

#### Intern Info

Vi er midlertidig udgået for 1506-1819 Stokkeholder Rep kit.

I stedet vil I modtage en ny stokkeholder.

Vi udsender ny information når vi igen har 1506-1819 Stokkeholder Rep Kit på lager.



**Klaus Smedegaard**  
Administrerende direktør



Regarding:  Crutch holder Repair Kit	PUP No.:	
	Prepared by:	LPA
	Date:	15-11-2023
	Internal <input checked="" type="checkbox"/>	External <input type="checkbox"/>

We are temporarily out of 1506-1819 Crutch holder Repair Kit.

In stead you will get a new Crutch holder.

We will send out new information when we have the 1506-1819 Crutch holder Repair Kit on stock again.



**Klaus Smedegaard**  
General Manager

